

Superfund Site Strategy Recommendation

Region 6

Site Name: Francis Oil Company, Inc. Site Number: TXD 068990340

Alias Site Name(s): _____

Address: 1500 S. Broadway

City/County or Parish/State/Zip: Carrollton / Dallas / TX / 75006

Recommendation:

FRANCIS OIL CO INC

TXD 068990340

1. No further remedial action planned under Superfund.

2. Further pre-remedial investigative action needed under Superfund:

PA _____ Priority: High _____ Medium _____

SSI _____

LSI _____

Other _____

To be performed by _____

3. Action may be appropriate under other authority: RCRA _____

NPDES _____ SPCC _____ 404 _____ TSCA _____ UIC _____

SIMCRA _____ State _____ Other _____

Discussion:

The site is an inactive gas station. It is surrounded by a network of pumps, transfer lines & underground storage tanks (USTs). The status & contents of the USTs are not known. The type & amount of mechanical work done at the facility is unknown; however, unless the work ~~was~~ was very large-scale, the quantity of any hazardous waste would be small. Drinking water in the area is from surface water, the intake for which is just within 15 miles downstream. There is one public supply well used for standby, completed at 2475 ft. in the Trinity Sands Aquifer. (The water level of the aquifer is assumed to be in excess of 1000 ft.). There is an alluvial aquifer less than 50 ft. deep, but there is no known usage. No sensitive environments exist within the area of concern. Based on the small waste quantity & the low potential for exposure through the various pathways, no further action under Superfund is warranted at this time. Investigative action by the State may be appropriate concerning the status & contents of the USTs on site. (Several inspections revealed fuel standing in the UST monitoring wells.)

Copies to (please list): TWC, ATSDR, 6W-S, 6E-E 

Recommended By: Linda Weber Date: 8/20/90

Approved By: Bill Taylor for Betty Williamson SUPERFUND FILE Date: 8/21/90

AUG 28 1992

9822833

REORGANIZED

